

to Chief Surveyors 23-1-17 Received from Chief Surveyors
 SEL'S NAME Shells Hanna Nielsen Report Seattle No. 477

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey _____ When due _____

❖ 100 A.F. (Steel)

2 DG (Steel)

Cell D.B. 356' 11986 F.P.T. 1206. A.P.T. 1406

FK. One B.H. in fore hold & One B.H. in after hold dispensed with. 5 B.H. only:

Can. A & P. P 44. B 115' F 47'

M
24-1-17

The Surveyors should be requested to state whether they are ^{correctly} reporting the figures in the cell D.B. page 52 check or whether there are as in the master vessel.

W^o

M



© 2020

Lloyd's Register Foundation

009122-009130-0174