

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME

Stl S OTTAWALITE

Rpt.

Indb

No.

85678

14064P

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

2275

Depth "d"

Framing: Table No.

Description

Longitudinal framing at
bottom and at deck2nd Longitudinal No.

8400

Proportions

Length

13.46

Depth =

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel). Carrying Petroleum in Bulk
for Service on the Great Lakes

1 D^x (Stl). Longitudinal framing at bottom and at deck

Cell D.B. & E 18' 24", A.P.T. 35.

F.K. 7 B.H. Centre line bulkhead non-oiltight, plenum pump. Classed ACP
machinery aft.



© 2020

Lloyd's Register
Foundation