

Steel Sc Luy "Bartmothian"

Submitted the Plymouth Surveyor he informed that Mr. Phillips has called at this office today and it has been arranged with him to fix a pillar to the beams at frame 7 on each side and also to the beams at frames 26 and 29. He should report to this office when this has been done to his satisfaction

for 13/7/15.



© 2021

Lloyd's Register  
Foundation