

trip switch as per Rule..... Generators, are they compound wound....., are they.....

GLASGOW REPORT No. 64862

S.S. "EMPIRE BAIRN"

The electrical equipment of this vessel has been fitted on board under special survey tested under full working conditions, and found satisfactory. All the requirements of the approved plans and the Ministry of War Transport specification have been carried out.

The materials and workmanship are good.

S. J. Indal

29th December, 1941.

009222-009231-0189

if of synthetic insulating material is it an A1