

done:- Ship placed in dry dock, shell plating, stern frame and rudder cleared and replaced.

- c o p y -

29th March, 1940.

JUN -6 1940

Mr. D. Turner,


Lloyd's Surveyor, deck dept.

(Signed) Y. Hasimoto,

S.S. "DETAGOA MARU".

Survey report her standing riggings of the masts.

All standing riggings is fairly good condition.



© 2021

Lloyd's Register
Foundation

Handwritten signature/initials

009278-009286-0187

Transverses.....

P.E.-G.

Floors.....

X

Keelsons.....

Have Watertight Doors been examined and found efficient? **Yes**

Transoms, Pointers & Crutches

„ leng
„ Rule