

5c.5.25.

TOORONG

F.E.

Inspected by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Stl oil barge No 66 Rpt. N.S.W. No. 1914

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. \_\_\_\_\_ Depth "d" \_\_\_\_\_

Framing: Table No. \_\_\_\_\_ Description angle frames as approved

Longitudinal No. \_\_\_\_\_

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = 10.40$

Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ A. I. (Steel). "Barge" "In Service in Sydney Harbour"  
 "Carrying Petroleum in Bulk"  
 1 Dk (Stl) "Web frames."  
 F.K, 5 B.H, LA. CP.

*[Handwritten signature]*

*[Handwritten signature]*  
8.2.27.



© 2021 Lloyd's Register Foundation

009341 - 009349 - 0064