

F.E.

Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____
 NAME Steel Crane Barge No. 542 Rpt. Rot No. 10770

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.

Transverse No. 69.14 Depth "d" -
 Siting: Table No. - Description Single Angle as approved
 Longitudinal No. 7951
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{8.76}{-}$
~~Deck~~ Sheerstrake as approved

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed

✱ A-1. (Steel) Crane Barge
 1 DK (Steel)
 pt. FK, pt BK $5\frac{1}{2}$ ", 5BK, Lem, A. CP
 Date of build 4.21

M *AD*
25.5.21



© 2021
 Lloyd's Register
 Foundation

009341 - 009349 - 0094