

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and plating, especially in the boiler space.

11

~~Steel Screw Steamer "SHOKO MARU"; No. 84062 in the Register Book; 2209 tons gross; Built in 1919; Port of Registry - Takasago; Owners: Showa Kisen Kabushiki Kaisha (Nisshin Kaiun Shokai, Managers)~~

Classed: 100A1 LMC 8,27
8,27 TS 8,27
s.s.No. 3-8,27

[Handwritten signature]

The Annual Boiler Survey of this vessel became due in August last, but the Owners have informed the Society's Surveyors at Kobe that it is not desired to maintain the steamer in the Society's Classification.

In the circumstances the Classing Committee, who had the case before them on Friday, 21st ultimo, decided to give instructions for the vessel's character to be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

[Handwritten signature]

3rd January, 1929.

DECLASSIFIED



© 2021

Lloyd's Register Foundation

009362-009375-0017

[Handwritten signature]