

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... Port of London

No. in Reg. Book 58384 Survey held at on the Wood, Iron or Steel Lk MAROC

Date, First Survey Last Survey 1899

By whom Cochrane & Sons, Ltd. When 1914 3

Owners J. Hurst. Owners' Address

Managers Port belonging to Bordeaux

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet Particulars of Classification

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed...

Last Report, No. 3605 Port BDX

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules.

Was a damage report made by anyone else? If so, by whom?

Table with columns: Shell Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items

Table with columns: State if Tanks have been examined inside, Dblig. Plates under Sounding Pipes

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification...

Fees applied for, Received by me.

Surveyor to Lloyd's Register of Shipping.

General Committee Thursday 21st April 1927

009376-009386-013