

5m, 9.24.

3 - FEB 1925

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

MARI
VESSEL'S NAME Stl. Sc. K. "JUAN ~~125~~"

Rpt. Bbo. No. 6620

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Bilbao Surveyors report this vessel placed in dry dock, the bottom cleaned and coated and one shell plate renewed.

It is submitted the vessel appears worthy to remain as classed with record of survey 1,25, as recommended.

100 A1 Steam Trawler

1.75 Bbo.

2.2.25.



© 2021

Lloyd's Register
Foundation

004505-009513-0089

1m, 2.4

Special Damage or
(per Sec. 20)

Travelling Expenses (if chargeable) £

Received by me.