

2nd 19.

1

how "Sarah A. Purdy"

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "JOHN HUMS".

Report Gla.

No 38647

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

100 A.L. (Steel) Steam Trawler.

1 Dk. (Steel).

DBf 29' 20t.

BK 7½. 3 BH. Cem. Lloyd's A. & C.P.



© 2021

Lloyd's Register
Foundation

17. 4. 19.

009505-009513-0337

Remainder in Holds.....

FISH HOLD.

Tie Plates, outside Hatchways.....

Deck * Material and thickness