

Rpt. 14.

Port of New York

November 5 19 46

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs:

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the S.S. **HABICUIS**; 7240 tons gross; Register of **Syra**; while afloat at Todd Shipyard, Hoboken, N.J.

I have to report that I found

Foremast: Port Shrouds # 1 & 2 good

Starboard Shrouds # 1 & 2 Good

Mainmast: All standing and running rigging good

Aftermast: All standing and running rigging Good

50 ton and 15 ton booms dismantled and gear stowed in after gear locker;

Emergency steering gear, blocks, sheaves, pins and shackles frozen and in unworkable condition;

Emergency steering gear, blocks, sheaves, pins & shackles freed and now placed in good order

W. J. V.

Fee \$25.00

To the Surveyors,
Lloyd's Register of Shipping,

Charles Tompkins



© 2021 Lloyd's Register Foundation