

Received at

Office

19

(Report on Vessel No. _____ Port _____)

I have to report that the undermentioned ~~Iron or~~ Steel Forgings or castings, manufactured by Nippon Steel Co. Ltd. Kawasaki for the Vessel No. 412, being built by Mitsubishi Shipbuilding Co. Ltd. of Kobe, Japan have been inspected by me as set forth below and found to be, so far as can be seen, sound

A. T. Thorne
Leith

	Tiller	RUDDER FRAME.	STEM.
1	STERN FRAME.		
0.4. Steel			
forged			
9 1/2" dia			
black			
on Inspection ...			
n Inspected	20 122.5. 25		
ASTINGS.			
" 1 Standard Test Pieces.			
Test—	31. 14		
or square inch	29		
on per cent. ...	180°		
ding Test—	✓		
before fracture	✓		
it—			
from ground ...			
ing Test—			
e according to Rules			
found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

e (if any chargeable) £ 1 : 11 : 6

To be paid at *Leith*

f Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.