

Date of writing Report 19... When handed in at Local Office 19... Port of *Gyona*
No. in Reg. Book *10309* Survey held at *on the Wood, Iron or Steel* SS. *GAELIC STAR* Master
Date, First Survey Last Survey 19...
(No. of Visits)
TONNAGE:- Built at *P. Glasgow* By whom *Russell & Co.* YEAR. MONTH.
GROSS *5596* Owners *Union Cold Storage Co. Ltd.* When 1917 8
UNDER DK. *5197* (Blue Star Line Ltd. Regn.) Port belonging to *London.*
NET *3327* Owners' Address
(If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; *uE&B* feet; *f* feet; *f* feet;
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Last Report, No. *117042* Port *Lon*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. *1100A1* *Shl.* *6-48* *TS N648C1*
* for Special Survey. *dk. with Shd.* *BS 8-48*
Date of last Survey and of Periodical Surveys. *SS 8-48-3-6-48* *120 Hahave 120° S.*
Society's Freeboard (if assigned) as painted on Ship and now verified *Ref. mch* ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE								
Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels.					
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)					
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month					
Coamings	Ceiling	Scuppers	Boats					
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.					
Outside Plating	Rudder	Hatches	Condition, how ascertained.					
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)					
Rivets	Windlass	Caulking ditto	Sails					
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter					
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. 0					
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)					
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	length size					
Floors		Ditto ditto at other places ditto	(on board) size					
Keelsons		Stringers, Clamps & Shells ditto	Rule length size					
Stringers		Salting ditto	Hawser & Warps					
Inner Bottom Plating		(State if examined.)	Standing & Running Rigging					

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pND15, &c."

Survey Fee (per Section 28) £	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29) £	10
Travelling Expenses (if chargeable) £	Received by me,
Second Surveyor's Fee (if any) £	10

Committee's Minute *30 SEP 1949*
Character Assigned *vide Gen*
Surveyor to Lloyd's Register of Shipping.
Special General Committee
Thursday, 13th October 1949
Lloyd's Register
duly confirmed
009640-009646-0021