

11. 6.

For the information of Surveyors and the Committee only.

Received at

Office

19

# Lloyd's Register of Shipping.

(Report on Vessel No. 22773 Port Rot.)

No. 556

## SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron~~ ~~Steel~~ ~~Castings~~ Castings, manufactured by **Nederlandsche Staalabrieken** of **Utrecht** for the Vessel No. **524**, being built by **Industr. My. "De Noord"** of **Alblasserdam** have been inspected by me as set forth below and found to be, so far as can be seen, **free from defects**

on Forgings or Castings.

Lloyd's Port of **AMSTERDAM**, 23rd January, 1934  
 r. No 1024 H.P.B. 13-12-33  
 pieces No. 1033 H.P.B. 2-1-34  
 brackets Nos. 1022/3 H.P.B. 13-12-33

*J. B. J. J. J.*

	1 STERN FRAME.	<del>RUDDER</del> <del>FRAME</del>	<del>SKEM.</del>
Material*		2 Connecting Pieces S.M. Steel	2 Prop. Brackets
Material made		Cast	
Annealed		Yes	
Dimensions		As per plan	
Progress on Inspection		Partly machined	
Time when Inspected	13th December, 1933; 2nd & 13th January 1934.		
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—	27,3 & 27,4	31,6	27,3 & 27,4
Tons per square inch			
Extension per cent. ...	34% 34%	30%	34% 34%
1 Bending Test—			
Angle before fracture		Good	
2 p Test—			
Height from ground ...	7 feet-good	-	
Numbering Test—			
If made according to Rules and found satisfactory ...		Good	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ : :

To be paid at **Amsterdam**



© 2020

Lloyd's Register  
 Foundation

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

30. T.

009674-009681-0256

Auxiliary Engines crank shafts, diameter as per Rule

as fitted

90 mm ✓