

S.S. "YEBOSHI MARU". No. 37629 in Register Book.

Kobe Report No. 399~~3~~.

The Surveyors report that the ordinary pillars at each side of each hatchway of upper deck have been removed at this survey and to compensate for this a girder has been fitted to hatchway coamings with built pillars at hatchway corners, as per blue print plan attached.

The scantlings and arrangements on this plan have been examined and compared with Rule requirements and are in order.

J.S.O.


16.8.23

© 2021

Lloyd's Register
Foundation

009743-009756-0072