

1m.12.15.

F.E.

Received by Chief Ship Surveyor 8.4.18

Received from Chief Ship Surveyor

VESSEL'S NAME Shells Shama

Rpt. Incl No. 30452

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 34.42

Depth "d" 11.58

Framing: Table No. 3 page 9

Description Simple angle as approved

Longitudinal No. 3786

Proportions Length = 8.5
Depth =

~~Deck~~ Sheerstrake 56 1/2 in instead of 32 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1 (Steel) Steam Tug as recommended

1DK

D.T. + 21' 30"

BK 7 1/2. 3BH. Can. Lloyd's Regd.

M 18
84



© 2021

Lloyd's Register
Foundation

009757-009770-0204