

Last Report No.

Port

LMC. New York.

*100A1 Shelter

2500.9.40.

ent to Chief Surveyors.....

Received from Chief Surveyors.....

ESSEL'S NAME "SERULA" Report Liv. No. 131735

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor LMC and BS When due LMC 8.50, BS 4.50

Two new Main boilers installed, Original removed.
Donkey Boiler and Evaporator removed from Vessel.
Noted.

JM

26/10/50

+ LMC 9.50, + NB 9.50.

Amend in R.B.

Delete 1 DB. 80 lbs.

HS 4080

MN 275.



© 2021

Lloyd's Register
Foundation

004771-004774-0150

The main feed pipes removed (tested).
and evaporator re