

1m.7.31.

1

Ver. 1827 1876

The class is subject to the Starboard oil fuel tank not being used until repaired

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

15 MAR 1932

VESSEL'S NAME *Salt Tug ST. FAITH*

Rpt. VER

No. 3161

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

ature of Survey

The *Vancouver* Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, and minor repairs effected.

The starboard oil fuel tank not dealt with at this time.
It is submitted the vessel appears worthy to remain as

classed with record of survey 2-32 as recommended. *Subject as above*

AI

For Towing purposes
2-32 Ver

Added for oil fuel

Subject to



© 2021

Lloyd's Register Foundation

15.3.32

009780-009788-0177

Transverses

Have Sluice Valves now been examined and found

Transoms, Pointers, & Crutches ditto

Cables (State if now