

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME STEEL S.S. "ST. FAITH" Report Liverpool No. 79546

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/6/82.*)

of Survey _____ When due _____

✱ A.1. (steel) "For Towing Purposes".

1 Dk (steel).

Cell DBa 17' 10t. FPT 26t. APT 38t.

BK 6". 3BH. Cem. Lloyd's A.&C.P. F 32'

Date of Build 6, 19.

The Surveyors should be requested to forward the usual Ship Fittings & Coasting report.

009780-009788-0202

Registered Tonnage ...

402.59	1139.83
11.32	32.04

Total ...

402.59