

Received from Chief Ship Surveyor.....

SHIP'S NAME Arimasan Maru.

REPORT

(2) Kob.
(3) Yka.
(1) Kob.

10590
4309
No. 10578

Outstanding Conditions of Class:

None.
Notation of S.S.(DR) C,C1 Withheld for Completion of S.S.

R.L. Appendix. (As before or ~~None~~)

Surveys due:

*Special Survey (D) due C,C1, largely held Kob 661
including drilling of shell & deck plating.
Postponement of completion of S.S. until about C,C2 approved
9-1-62.*

Structure of Present Survey: (Afloat and in dry dock)

- (1) Docking & completion of Special Survey (D). W & T. repairs.
- (2) Deferred repairs to collision damage.
- (3) Docking & temporary repairs to collision damage.

Special Features:

*The thicknesses of shell & deck plating as ascertained by
drilling & reported by the Surveyors previously approved.*

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S.)

None

S. to be completed by:

Recommendation:

*Submitted record of DS. C,C2 and notation of S.S.(DR) C,C1
be assigned subject to indented and (holed) shell plates D19,
E19 and stem plating (S.S. from aft) also to indented shell
plates D18 & 19, C11, E19 & 20, F19, G20. and structure in way
of forepeak tank (p.s. from aft) being dealt with at the
next drydocking.*

*DS. C,C2. Subject.
S.S.(DR) C,C1.*

In S.R.L. Appendix.

*Shell plates A11 & 12 (S.S.) in way of
No 1 & 2 O.B. tanks slightly corrugated.*



© 2020

Lloyd's Register
Foundation