

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 59486 Survey held at on the Wood, Iron or Steel Date, First Survey 1918 Last Survey 1918  
 By whom Stevenson & Asher Master  
 TONNAGE: GROSS 94 Built at Canf. Owners' Address J. Strachan When 1918 MONTH 10 mo.  
 UNDER DK. 93 Owners' Address J. Strachan Port belonging to Peterhead  
 NET 41 (if not already recorded in Appendix to Register Book). Managers

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock Abn Destined Voyage  
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
 CHARACTER. + 11 A1. Machinery and Boiler Surveys (including date of N.B., if any). + Dec 9. 20.  
 Date of last Survey and of Periodical Surveys. For Fishing purposes. T.S. 3.22 c.c.  
4.22.

N.B.—All alterations in the existing records should be underlined.  
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Damage cases where the Surveyor has not made a special damage report he required to state whether he offered his services for this purpose and to whom and why they were declined  
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.  
 Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

ARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ... ..								
Removed and Fairred or Repaired ... ..								
Faired or Repaired in place ... ..								

NT CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
g of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
ays	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
gs	Ceiling	Scuppers	Boats
& Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Plating	Rudder	Hatches	Condition, how ascertained
y of ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
ocks & Crutches	Windlass	Caulking ditto	Sails
s	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
s	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
tom Plating	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
		Ditto ditto at other places ditto	„ Rule length size
		Stringers, Clamps & Shells ditto	Hawser & Warps
		Salting (State if examined.) ditto	Standing & Running Rigging

eral Observations, Opinion as to Class, Recommendation, &c.:—  
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c.”

Amount	Fees applied for
£ : : (per Section 29)	19
£ : : Damage or Repair Fee (if any) (Sec. 29)	Received by me.
£ : : Expenses (if chargeable)	19
£ : : Surveyor's Fee (if any)	

Committee's Minute **FRI. 12 DEC 1924**  
 Character Assigned withdraw class  
Write down Co. 18/12/24 insert  
Abn

Surveyor to Lloyd's Register of Shipping.  
 General Committee  
 Thursday, 18th December, 1924  
 Lloyd's Register  
 Classification Committee  
 decision confirmed

To Certificate required? If so, to be sent to