

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Cette Corabe

Rpt.

1907
13590

No.

13590

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

oil engines 4 sc. la.

If Boilers fitted with forced draught

no Boilers

Tail Shaft. If fitted with a continuous liner

no

If fitted with an outside gland of

approved type

Yes

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ Rule 12-36.

Submitted the Surveyor he asked to forward the best certificates for the Squeamors & to state how the Centrifugal pumps are driven.

*Re The Cardiff Surveyor report
re examination of the propeller
fastenings after grounding
2 propeller blade is slightly damaged*



© 2021

20/1/37

Lloyd's Register
Foundation

009896-009903-0049