

~~D/E~~ ^{1 B/E}
DS 699

New * MIRONYCH * F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl & MICHAEL TOMSKY Rpt. Len No. 12

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.* - Extract from Sub-Committee's Report, 24/5/92.)

^{1st Long}
Transverse No. 6251 Depth "d" 19.7

Framing: Table No. ✓ Description Channel frames as approved

^{2nd} Longitudinal No. 18120

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 12.2

Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

* 100A.1. (Steel).
1 Dk (Stl). Strengthened for navigation in lee
Cell D.B. 228' 525t, F.P.T. 43t, A.P.T. 91t
FK, 4 B.H, pt cem, Plyds A.C.P.
P 14', B 68', F 24'.

[Signature]
10.10.27.



© 2021

Lloyd's Register Foundation

009904-009911-0107