

F.E.

Ship Surveyor _____ Received from Chief Ship Surveyor _____

E Stl & M.V. "OLYMPIA MARU" Rpt. Hag. No. 1603

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Erse No. 12960 Depth "d"
g: Table No. Description Bull angle frames as approved.
tudinal No. 35235
Proportions Length 12.66
Depth =
Deck Sheerstrake as approved.

Revised Rules.

This vessel appears to have been built in accordance with the
s and the approved plans, and it is submitted she is eligible to
classified

✠ 100 A. I. (Steel).
2 D^{ks} (Stl).
Cell D.B. 347' 12155, D.T.a 28' 7355, F.P.T. 126t, A.P.T. 335.
F.K, "Intermediate tween D^{ks} B.H in after hold dispensed with
H B.H to upper D^{ks}, 2 BH to 2nd D^{ks}. pt Cen, Lloyds A.C.P.
P 58', B 110', F 41'.



009934-009942-0300