

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRSReceived London
2954 32

Ship's Name ~~XX~~ MS "NUOVA AUSILIATRICE"
Ex "CAIRNGORM"
Gross tons 400

Is there a rpt. 9? Port Glasgow Rpt. No. 94156.

No. of visits One First date - Last date 6.12.62.

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) 94155-95.

Date of completing rpt. 18.12.62. Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? Yes Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (RR); (Rig) (P.S.)

Survey fees - Damage fee - Expenses

Date entry made in RFB.

Surveyor's Initials.

S.A. fee -

I have surveyed the above ship in accordance with the Rules for Change of Ownership and nationality.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Conditions of Class:- Nil

S.R.L. (Appendix) - indented shell plates G.1 & G.2 (p.s.f.)
and keel and 'A' strake landing (p.s.)
set up about 1" over a length of 20'-0".

Change of Owner - Vessel renamed "NUOVA AUSILIATRICE"
Port of Registry - Trapani.

Owners Name & Managers. - Surdo Giovan-Battista.
Trapani.

MEMO FOR
PUBS. NO. 200

I recommend that this ship remain as classed ~~with~~/without fresh record of dry docking and
without special condition.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute DS. 11.62, without Spl. Cond.

Surveyor to Lloyd's Register of Shipping

(J. E. I. DEIGHAN)

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

8 (P.S.) DRY CARGO SHIP

Ship's Name ~~XX~~MS "NUOVA AUSILIATRICE"
Ex "CAIRNGORM".

S.S. () Due

Port Glasgow

Rpt. No.

Examined & condition		Examined & condition	
try dock from	} No	* Air & sounding pipes	Yes (Above deck) Good
" " to		Doublers under " "	Not examd.
Shell plating		Steering arrangements (main)	Not examd.
Sternframe		" " (aux)	Not examd.
Rudder	} Not	Windlass	Not examd.
Rudder lifted?		Masts & rigging	Yes (From Deck) Good
ing, etc. in way		Hand pumps & suction	Not examd.
shell openings		W.T. doors	Not examd.
Side scuttles & deadlights	} Examd.	Bulwarks, freeing ports, etc.	Yes - Good
erbd. scuppers & discharges			
F.P. spaces		Summer freeboard as verified	3'-8" /
Chain locker			
A.P. spaces	} EQUIPMENT:	Equipment letter	(f)
Engine space		Fee ltr., if diff. from eqpt. ltr.	-
Boiler space		Anchors: No. on board	2B. IS
Under E. & B.		State if ranged	No
Coal bunker	} Cables	Length on board	Stated complete
Tunnel & well		Mean dias. range from	- to -
ement, asphalt, e., on btm. shell		Rule length	- Dia. -
Weather decks		Mooring ropes	Sufficient.
* Casings	Yes - Good		
* Deckhouses	Yes - Good		
Superstructures	None		
* Skylights	Yes - Good		
Companionways	Yes - Good		
* Hatchways	Yes - Good		
* Ventilators	Yes - Good		
Other items:			

must be stated a
ately from wear a
what action has be
Any alterations

OTHER ITEMS:

These items to include their closing appliances
Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

J. E. I. Deighan
Surveyor to Lloyd's Register of Shipping
(J. E. I. DEIGHAN)

0284 2/12

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	Yes Pt. Examd. Good	F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
No. 4	Hold		Settling tanks		
"	'Tween decks				
No. 5	Hold		Deep tanks		
"	'Tween decks				
No. 6	Hold		Side tanks		
"	'Tween decks				
			Wing tanks		
			Other tanks:		
Cargo battens		Pt. examd. Good			
Ceiling, etc.					



© 2021

Lloyd's Register
Foundation

Where
be retain
must be
Date of
Minute