

Received London
28th Jan 62

Ship's Name ~~S.S.~~ "NUOVA AUSILIATRICE"
Ex "CAIRNGORM" Gross tons 400

here a rpt. 9? Port Glasgow Rpt. No.

No. of visits One First date - Last date 7.12.62.

in Cert. issued Damage rpt. issued & copy herewith? Yes No Last rpt. (H.Q. only)

Date of completing rpt. 18.12.62. Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

as a Load Line survey been held? Yes Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (~~Cont~~); (PS); (~~DR~~); (~~EC~~); (Rig) (P.S.)

Survey fees - Damage fee - Expenses

S.A. fee -

Have surveyed the above ship in accordance with the Rules for Change of Ownership and Nationality.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Conditions of Class:- Nil

S.R.L. (Appendix) - Indented shell plates G.1 & G.2 (p.s.f.) and keel and 'A' strake landing (p.s.) set up about 1" over a length of 20'-0".

Change of Owner - Vessel renamed "NUOVA AUSILIATRICE"

Port of Registry - Trapani.

Owners Name & Managers. - Surdo Giovan-Battista, Trapani.

I recommend that this ship remain as classed ~~with~~ without fresh record of dry docking and without special condition.

OTHER ITEMS	BEAMS	DECK PLATES	FRAMES	SHILL PLATES	DAMAGE REPAIRS	ALSO FOR
						SPL FOR
						TRO
						SRL
						POSTING
						HEADER
						CERT

Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

J. Deighan
Surveyor to Lloyd's Register of Shipping
(J. E. I. DEIGHAN)


Lloyd's Register Foundation

010012-010023-0285 1/2

Ship's Name **SSMS "NUOVA AUSILIATRICE"** S.S. () Due
Ex "CAIRNGORM"
 Port **Glasgow** Rpt. No. _____

Examinated & condition	Examinated & condition	
Dry dock from } No to } Shell plating Sternframe Rudder rudderlifted? ing, etc. in way shell openings Side scuttles & deadlights erbd. scuppers & discharges F.P. spaces Chain locker A.P. spaces Engine space Boiler space Under E. & B. Coal bunker Tunnel & well cement, asphalt, e., on btm. shell Weather decks * Casings * Deckhouses Superstructures * Skylights Companionways * Hatchways * Ventilators Other items:	* Air & sounding pipes Yes (Above deck) Good Doublers under Not examd. Steering arrangements (main) Not examd. (aux) Not examd. Windlass Not examd. Masts & rigging Yes (From Deck) Good Hand pumps & suction Not examd. W.T. doors Not examd. Bulwarks, freeing ports, etc. Yes - Good Summer freeboard as verified 3'-8" <u>EQUIPMENT:</u> Equipment letter (f) Fee ltr., if diff. from eqpt. ltr. - Anchors: No. on board 2B. IS State if ranged No Length on board Stated complete Mean dias. range from - to - Rule length - Dia. - Mooring ropes Sufficient.	
	Not	
	Examd.	

These items to include their closing appliances
 Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

© 2021

 Lloyd's Register
 Surveyor to Lloyd's Register of Shipping
 (J. E. I. DEIGHAN)
 Foundation

0285 2/2

HOLDS & TWEEN DECKS:	Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold Yes Pt. Examd. Good Tween decks	F.P. tank A.P. tank D.B. tanks & c/dams		
No. 2	Hold Tween decks			
No. 3	Hold Tween decks	O.F. bunkers Settling tanks		
No. 4	Hold Tween decks	Deep tanks		
No. 5	Hold Tween decks	Side tanks		
No. 6	Hold Tween decks	Wing tanks		
	Cargo battens	Other tanks:		
	Ceiling, etc.			



Surveyor to Lloyd's Register of Shipping
(S. S. I. DEPARTMENT)

0582-15