

F.E.

of Ship Surveyor.....

Received from Chief Ship Surveyor.....

NAME Stl S VENDEMIAIRE Rpt. Itam No. 18800

Works of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Perse No. 16767Depth "d" ✓g: Table No. ✓Description Full angle frames as approveditudinal No. 45428Proportions  $\frac{\text{Length}}{\text{Depth}} =$  12.9~~Deck~~ Sheerstrakeas approvedRevised Rules

This vessel appears to have been built in accordance with the  
and the approved plans, and it is submitted she is eligible to  
ssed

✠ 100 A.I. (Steel). Carrying Petroleum in bulk

10" (Stl). Rudder Electrically Welded.

Cell D.B. E 57' 1815, D.T. 47' 766t, F.P.T. 1825, A.P.T. 1285

F.K. 11 B.H., pt. cen, Lloyd's A.C.P.

P 108', F 40'. Machinery aft.



© 2021

Lloyd's Register  
Foundation

010037-010045-0100