

Lloyd's Register of Shipping.

ALL-51


REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship S.S. "FUJI MARU" Official Number 63992 Port of Registry TOKYO
 Place of Survey Mukaijima Dates of Survey 24-5-51. Date of last Load Line Survey May 1950

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners	Good		
Beams	"		
Fore and afters	None		
*Covers	Good	50 hatch covers renewed.	24-5-57
*Tarpaulins (State number per hatchway)	" (3)		
*Cleats and battens	Good	1 cleat & 1 ring renewed.	24-5-57
Lashings and their fittings	"		
Wedges (Is supply, including spares, adequate?)	"		
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	Good		
Beams	"		
Fore and afters	None		
*Covers	Good		
*Tarpaulins (State number per hatchway)	" (3)		
*Cleats and battens	"		
Lashings and their fittings	"		
Wedges (Is supply, including spares, adequate?)	"		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	Good		
Beams	"		
Fore and afters	None		
Covers	Good		
Tarpaulins (State number per hatchway)	" (2)		
Cleats and Battens	Good		
Wedges (Is supply, including spares, adequate?)	"		
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings their supports and deck connections	Good		
Closing arrangements	"		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings their supports and deck connections	Good		
Closing arrangements	"		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good		
7. Within partially enclosed superstructures.			
Closing arrangements	None		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	Good		
Skylights, their fastenings, covers and lashings	"		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	Good		
11. Within partially enclosed superstructures.			
Doors and fastenings	Good		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	X Good		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



© 2021

Lloyd's Register Foundation

010037-010045-0148

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	Good		
Bridge, fore end	"		
Bridge, after end	"		
Poop	"		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	None		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good		
17. SIDE SCUTTLES AND DEADLIGHTS...	"		
18. GUARD RAILS	"		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways... ..	Good		
20. LIFELINES (fittings and material)...	Good (Manila Ropes)		
21. FREEING PORTS.			
Shutters	---		
Portection bars	---		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances... ..	None		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
24. LOAD LINE MARKS	Verified		

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. (§ Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
ALL	<i>M. Lamakura</i>	MUKAIJIMA	24/5/51.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

(i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and

(ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Certificate and the certified copy as follows:—

Signature of Surveyor *M. Lamakura* Place Mukaijima Date 24/5/51.

Signature *M. Lamakura*

Date 1/6/51.

G.H.W.
13 OCT 1951

Fee ¥ 2000.00

Number of Visits 2

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.

