

29857

010037-010045-0220

25081

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office) SAT. - 7 JUL. 1917

Port *Dull.*

Vessel's Name *S/S. MARY BIRCH.*

684

Official No. *v*

No. in Reg. Book

XB in Supp.

Port of Registry (~~For Foreign Vessels~~) *Dull.*

Iron or Steel *steel*

State whether Classed by Lloyd's Register

Class contemplated

Name of Owners *S. F. Birch & Son Ltd*

Date of Verification

July 6th 1917

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	—	ft.	<i>8 1/2</i>	ins.	✓
From centre of disc to top of statutory deck line	}	✓	ft.	✓	ins.
at awning or part-awning deck					
Fresh water line above centre of disc			<i>2 1/2</i>	ins.	✓
Indian Summer line above centre of disc			✓	ins.	
Winter line below centre of disc			<i>1 1/2</i>	ins.	✓
Winter North Atlantic line below centre of disc			✓	ins.	
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	}	at main, spar or upper dk.	✓	ins.	✓

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Marked & verified in accordance with Peep's assignment letter M 27/3/17.

W. H. Aspinall Surveyor.

(To be filled up in London Office.)

Statement No. *25081* Date of Committee's Minute *27.3.17*

Moulded Depth for record *11* ft. *0* ins.

Freeboards compared and found correct by *W.H.A.* date *9.7.17*

Is fee paid? *New vessel* Form for Certificate

Instructions *Write Certificate & Post.* date *9.7.17*

Certificate written *9-7-17* Noted for posting

Freeboard for record = 10-8 1/2"

Draught " " = 10-6

