

N/M KALITICH

D/8312

F.E.

Im, 12, 15.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Success. Mary Birch

Rpt.

1st

No. 30144

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

32.42

Depth "d"

8.5

Framing: Table No.

3. page 9

Description

Single angle

Longitudinal No.

3566.

Proportions

Length

10.

Depth

Deck Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100 A-1 (Steel) as recommended

1 DK. (Steel) & Well Deck.

Cell DB + 65' 80L.

FK. 4BH. on 25' B 9' F 15.

Keel and P.



© 2021

Lloyd's Register Foundation

010037-010045-0231