

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ^{AND}_{OR} PASSENGER SHIPS.

When received in London Office.....

17 JUL 1947

Port ValenciaName S/S. "MIRAFLORES"

Official No.

No. in Reg. Book 78785Port of Registry BilbaoGross Tonnage 3209Signal Letters E.A.H.D.Iron or Steel SteelState whether Classed by Lloyd's Register YesName of Owners Cia. Nav. VascongadaDate of Verification 7.7.47

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

FREEDBOARD AMIDSHIPS FROM TOP OF DECK LINE WOOD/STEEL ^{UPPER} DECK.		FROM CENTRE OF DISC.	
Tropical Fresh Water.	<u>57.32"</u> ft. <u>948 mm/m</u>	<u>265 mm/m</u>	above <u>10.43"</u>
Fresh Water	<u>41.82"</u> ft. <u>1062 mm/m</u>	<u>151 mm/m</u>	above <u>5.93"</u>
Tropical	<u>43.25"</u> ft. <u>1099 mm/m</u>	<u>114 mm/m</u>	above <u>4.50"</u>
Summer	<u>47.75"</u> ft. <u>1213 mm/m</u>		
Winter	<u>51.75"</u> ft. <u>1315 mm/m</u>	<u>102 mm/m</u>	below <u>4.00"</u>
Winter North Atlantic	ft. <u>/</u> ins. <u>/</u>	ins. <u>/</u>	below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

[Signature]
Surveyor.

(To be filled up in London Office.)

Statement No. Date of Committee's Minute 18:10:32.

Particulars for Record in Register Book.	Moulded Depth	<u>25</u>	ft. <u>6</u>	ins.
	Freeboard	<u>3</u>	ft. <u>11 3/4</u>	ins.
	Corresponding Draught.	<u>21</u>	ft. <u>9</u>	ins.

Freeboards compared and found correct by E. Date 17 JUL 1947Is fee paid? Form for Certificate Spanish: - 31:10:50Certificate written 24:6:46 Noted for posting Postea.

010056-010066-0046