

m.7.40.

ss Tama No. 2-38.

ely's Freeboard (if assigne
painted on Ship and now ve

If so, by whom?

ceived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME..... HAKONESAN MARU

Rpt. Kob

No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Comm. e, engine

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The KOBE Surveyors report the vessel placed in dry dock, bottom coated and the greater part of the 1st S.S. No. 3, due 6.41, held.

It is stated the Survey will be completed by the Spring of 1942.

Some internal riveting dealt with, and minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.41.

100A1
3.41 Tama
Carrying cargo oil
etc. in deep tanks



© 2020

S.S. PART HELD

Lloyd's Register
Foundation

Bo A/No
5/8/41

010137-010149-0085

Y.M.
if or
at or
Mas.
as.
Cop
how
lett
o. of
her
State
length
(on b
Rule len