

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME Stl & <sup>M/V</sup> "SIGRID"

Report Stl No. 48540

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey 1<sup>st</sup> Entry When due \_\_\_\_\_ Revised Sub

• 100 A. I. (Steel) Carrying Petroleum in Bulk.  
D<sup>c</sup> (Stl) + Web Frames. Strengthened for navigation in ice  
el DB, E 44' 68t, F.P.T. 36t, A.P.T. 13t.  
E.K, 10 B.H, pt Cem, Lloyd's A & CP.  
x 71', TRUNK 91', F 4' 5". machy aft.



© 2020

Lloyd's Register  
Foundation

010200-010207-0099