

For the information of Surveyors and the Committee only.

Received at

Office,

19

Lloyd's Register of Shipping.

(Report on Vessel No. 110 Port Vancouver)

No. 261. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron~~ Steel Forgings ~~Castings~~ manufactured by Burns Dry Dock Co of North Vancouver for the Vessel No. 110, being built by Burns Dry Dock Co of N. Vancouver have been inspected by me as set forth below and found to be, so far as can be seen, sound & free from defects.

on Forgings ~~Castings~~.

Lloyd's
No. 261.
21. 8. 26 AS.

A Scott

Vancouver
Rudder main piece

STERN FRAME.

RUDDER FRAME

STEM.

Material* ...
made ...
Dimensions ...
Process on Inspection ...
When Inspected ...
CASTINGS.
Tests on Standard Test Pieces.
Tensile Test—
Tons per square inch ...
Extension per cent. ...
Bending Test—
Angle before fracture ...
Impact Test—
Height from ground ...
Swaging Test—
If made according to Rules and found satisfactory ...

Iron
forged-annealed.
to drawing
machined
17. 5. 24. 21. 8. 26

29.98 tons
34.5

180° without fracture

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £
To be paid at Charged.



© 2021

Lloyd's Register
Foundation

If of Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.

010219-010228-0151

Inner surfaces drain way.

Is there a drain arrangement fitted at the lowest part