

401 Mmo.

# Lloyd's Register of Shipping.

(Report on Vessel No. 1191 Port Malmö)

## No. 3981 SHIP ~~FORGINGS~~ OR CASTINGS.

We have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs Skandinaviska Stålfabriks AB of Hallands, <sup>Ref. nos.</sup> Kanarokölen for the Vessel No. 171, being built by Kockum's Mek. Werkstad. of Malmö, Sweden. have been inspected by <sup>us.</sup> ~~me~~ as set forth below and found to be, so far as can be seen, sound.

Castings despatched to Messrs John Harvie & Co. Ltd., Greenock.

Mark on Forgings or Castings.

Lloyd's  
No. 3981  
U.S.L. 17.6.31.

*William Cairns*  
*Chas. S. Porter*

1 Filler


	<del>STERN FRAME.</del>	<del>RUDDER FRAME.</del>	<del>STEM.</del>
Material*	<u>Stemens-Martin Acid, Open Hearth Steel</u>		
How made	<u>Cast.</u>		
If annealed	<u>Annealed</u>		
Dimensions	<u>Top pattern</u>		
Progress on Inspection	<u>Rough Machined.</u>		
Date when Inspected	<u>22/5/31 - 17/6/31.</u>		
CASTINGS.	<u>Lot No 770</u>		
Tests on Standard Test Pieces.			
Tensile Test—			
Tens per square inch	<u>29.2</u>		
Extension per cent. ...	<u>32.0%</u>		
Cold Bending Test—			
Angle before fracture	<u>120° WF.</u>		
Drop Test—			
Height from ground ...	<u>10 feet</u>		
Hammering Test—			
If made according to Rules and found satisfactory ...	<u>Yes</u>		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ - 10.6.

To be paid at Gls. a/c. 22/4/31.

Register of Shipping  
**MALMO**  
15-1931.  
Surveyors Office



© 2021

Lloyd's Register

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

*London*  
*Sweden*

