

source of danger.

LLOYD'S REGISTER.

t of the Piping of Patent Circulator removed from the


S.S. " ANGL O SAXON'S " Donkey Boiler.

s boiler stated to have been working about 6 weeks from
s time circulator had been fitted until removal of same.

least half of this time under banked fires; the deposit
ing the result of about 3 weeks steaming.

© 2021

John Rolston



Lloyd's Register
Foundation

010276-010282-0191

As now

TUE 10 FEB. 1920

TUE. MAR.