

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

20 JUL 1959

4E

SHIP'S NAME.....

FUKUZAN MARU

REPORT.....

Smk

No. 971

MBS due 7.59, now held.

Docking. Tailshaft seen.

The Surveyor reports some repairs effected to the boilers, and in the case of the centre boiler, the centre and port furnaces found slightly deformed and hoop rings now fitted on Nos. 3 and 5 corrugations in each furnace.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh records of MBS 6.59 and TS (CL) 6.59.


16.7.59



© 2021

Lloyd's Register
Foundation

010294-010294-0113