

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

Vessel's NAME *Stlts PERIJA* Rpt. *hmc* No. *81967*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

5032

Depth "d"

Framing: Table No.

Description *Longitudinal framing as approved*

Longitudinal No.

20282

Proportions

Length

18.5

Depth =

Deck Sheerstrake

*as approved**Lensel Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.I. (Steel). Carrying Petroleum in Bulk
 10" (Stl) - web frame. Longitudinal framing
 Cell D.B. & E.B. H2' 1075, F.P.T. 1945, A.P.T. 855.
 F.K. 11 B.H. pt cm, Lloyds A.C.P.
 { P 69' B 22' F 33' } machy aft
 TRUNK 181

It is concluded the stream ~~has~~ been supplied but the
 Surveyor should be requested to state if this is so.

010300-010308-0047