

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Stl. Sc. "HARMATRIS"

Report

Grk

No. 19411

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due

✓

✦ 100 A1 (Steel)

1 D^K. (Stl)

bell DB a&uE 158' f 189' 1397t FPT 167t. APT. 240t

FK. 7BH. cem. Lloyd's A&CP.

P 41' B 270' F 38'



© 2021

Lloyd's Register
Foundation

010328-010337-0176