

Inspected by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME _____

Koryu Maru.

Rpt. _____

Kag.

No. _____

1808.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Type of Engine _____

oil engine 2 S.C.S.A.

If Boilers fitted with forced draught _____

Tail Shaft. If fitted with a continuous liner _____

If fitted with an outside gland of _____

approved type _____

*Yes.**No*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *UNCL 12.31.*

*AD 1004**27 12/13**P. J.*

© 2021

Lloyd's Register Foundation

010369-010377-0213