

ed by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME Campodon Rpt. Blo. No. 8488

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Type of Engine C. 4 G. 13 1/2" x 27" — 18"
94 NHP.

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
 approved type

Yes
 Yes
 No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +LMC 5.34

Fitted for oil fuel 5.34, F.P. above 150°F.
2 B 125 lb.

L.L.
20/6/34.

S.H.



© 2021

Lloyd's Register
 Foundation

010440 - 010450 - 0050

...liquid to retain a good



© 2021
Lloyd's Register
Foundation

Handwritten signature or initials.

Handwritten text, possibly "A42".

Handwritten text, possibly "1/2 1/2 1/2".

Handwritten text, possibly "1/2 1/2 1/2".

Handwritten text, possibly "1/2 1/2 1/2".

Handwritten text, possibly "1/2 1/2 1/2".

Handwritten text, possibly "1/2 1/2 1/2".