

Received from Chief Ship Surveyor

11 - JUN 1956

NAME "SKELJUNGUR" REPORT Rot. No. 41326

ending Conditions of Class: NONE.

ement of Class (B) (~~As before~~ or None)

of Present Survey: (~~As before~~ in dry dock)

Docking. *Damage (grounding)*

endation:

SUBMITTED record of docking 4,56 be assigned,
with Endorsement (B).

4,56 Rot.

ENDORSEMENT OF CLASS (B).
No.2 keel plate, from aft,
slightly set up.

Blk (new)

Inner Box
Have the ?



© 2021 *SK*
22-5-56

Lloyd's Register
Foundation

010484-010494-0106