

81  
15

F.E.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *Stl T.S. APURE* , Rpt. *nuc* No. *82740*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

*1<sup>st</sup> Long*  
Transverse No. *5174*

Depth "d" ✓

Framing: Table No. ✓ Description *Longitudinal framing*

*2<sup>nd</sup>* Longitudinal No. *23049*

Proportions Length ✓  
Depth =

Deck Sheerstrake *as approved*

DISCLOSED  
SECTION  
No. 780

*Revised Rule*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel). Carrying Petroleum in Bulk  
10" (Stl) web frames, Longitudinal framing, Bracketless System  
Cell D.B. E. B 50 149t, Side tanks 180' 2115t, F.P.T. 2076, A.P.T. 126t  
F.K., 8 B.H., pt cen, Clays A/CP  
P 73' B 22 F 40' machy aft.  
TRUNK IN WELLS



© 2021  
Lloyd's Register  
Foundation

*J.S.*  
*H.S. 28*