

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl S ANGLO AFRICAN* Rpt. *Sld* No. *30224***The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

ure of Survey

This vessel has left Sunderland for the Tyne to have the machinery installed.

It is submitted the Newcastle Surveyors (who have been advised) be requested to forward a report on form 8 when the survey has been completed.

Rtd. Sld + Wve. 16/12

It is concluded the height of the tank side brackets in way of the deep tank is as approved but the ^{the} Surveyors should be requested to state if this is so.

010563-010571-0290

© 2021

Lloyd's Register Foundation