

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port _____)

No. 6760. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or~~ Steel Forgings ~~or~~ Castings, manufactured by Messrs. Burmeister & Wain of Copenhagen for the Vessel No. 346, being built by Messrs. Burmeister & Wain of Copenhagen have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects.

One Rudder main Piece 2 Arms.

n Forgings or Castings.

Lloyd's
No. 8430.
K 3.2.27.

Copenhagen, 10th March 1927.

S. Clausen
SURVEYOR TO LLOYD'S
REGISTER OF SHIPPING

	STERN FRAME.	RUDDER FRAME	STEM.
Material	/	S. M. I. Steel.	
Made at		Hydraulic forged.	
Dimensions		As per plan.	
Process on Inspection		Forged - finished.	
When Inspected		3/12 16/2.26 19/1 3/2.27.	
CASTINGS. on Standard Test Pieces.			
Tensile Test - Tons per square inch			29.3
Elongation per cent. ...		2.2	29.9
Bending Test - Degrees before fracture		180°	good.
Weight from ground ...			✓
Welding Test - Made according to Rules and found satisfactory ...		✓	


SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

See (if any chargeable) £ ✓

To be paid at ✓

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

State if annealed. yes.



© 2021

Lloyd's Register
Foundation

010605-010614-0135

01060

C.P.M. REPORT No 7486.

Ms. MINNIPA

OF PORT ADELAIDE.



© 2021
Lloyd's Register
Foundation