

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... 24 AUG 1959

SHIP'S NAME..... KOMEI MARU..... REPORT..... Kob. No. 6837

ES due 8.59 now part held.

MBS, DBS, TS and SPS now held.

The Surveyor reports temporary repairs to ballast pump cylinder and valve box and recommends their renewal by 6.60.

IT IS SUBMITTED that this vessel is eligible for the record AES 6.59, on completion as form 8E MBS 6.59, DBS 6.59, TS 6.59 and SPS 6.59 subject as now recommended.

JL.

24.8.59.



© 2021

Lloyd's Register Foundation

010615-010623-0083