

Rpt. 12.

Copy FREEBOARD VERIFICATION FORM FOR STEAMERS. (When received in London Office)

Port

Vessel's Name

Mudela No 2

No. in Reg. Book

36 Suff

Official No.

Port of Registry (For Foreign Vessels)

Bilbao

Iron or Steel

State whether Classed by Lloyd's Register

100A.1. Awaiting Dk with freeboard

Name of Owners

Date of Verification

28 Sept 1916

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	ft.		ins.
From centre of disc to top of statutory deck line } at awning or part awning deck	7	ft.	6½ ins.
Fresh water line above centre of disc			4 ins.
Indian Summer line above centre of disc			2 ins.
Winter line below centre of disc			2½ ins.
Winter North Atlantic line below centre of disc			4½ ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.		— ins.
	at awning or pt. awning dk.		1½ ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Surveyor.

(To be filled up in London Office.)

Statement No.

Date of Committee's Minute

Particulars for Record in Register Book.

Moulded Depth

23 ft. 4 ins.

Freeboard

7 ft. 6½ ins.

Corresponding Draught

16 ft. 1 ins.

Freeboards compared and found correct by

date

Is fee paid?

Form for Certificate

Instructions

date

Certificate written

Noted for posting

Compulsory freeboards a condition of classification



© 2021

Lloyd's Register

Foundation