

GRANNY SUZANNE *Magwood*

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Sd S* ^{EX} IRON CHIEF, Rpt. *Sd.* No. *30385*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

^{1st Long} Transverse No. *10438* Depth "d" *25.10*

Framing: Table No. _____ Description *Bull angle frames as approved*

^{2nd} Longitudinal No. *29859*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *13.05*

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel)

1 D° (Stl)

All D.B a + U E 126' x 169' 10605, F.P.T. 1735, A.P.T 1655.

F.K, 6 B.H, Cem, Rlays A/CP.

P 30', B 110', F 36'.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register Foundation

010640 010651 0295

16.6.30