

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Pentola

Rpt.

*Aus
Rot
Aus.*

No.

*13640
24298
13624*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

*Oil Engine 4. S.C.S.A**126 cy. 11 $\frac{13}{16}$ " - 18 $\frac{7}{8}$ "*

If Boilers fitted with forced draught

no main boiler

Tail Shaft. If fitted with a continuous liner

*ye*If fitted with an outside gland of
approved type*no*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ L.R.C. 3. 36**O.B. 180 lb.*

*Y
J. J. 36*



© 2021

Lloyd's Register
Foundation

010755-010765-0025